DEPT. OF TRANSPORTATION DOCKETS

[4910-13-U]

[4910-13-0]	
DEPARTMENT OF TRANSPORTATION (DOT) 2005 APR 14 P 3: 15	CONCURRENCES ROUTING SYMBOL
Federal Aviation Administration	AVMII6 1)
14 CFR Part 39 [Docket No. FAA-2005-±±+++; Directorate Identifier 2003-NM-103-AD]	DATE
[Docket No. FAA-2005-±±+++; Directorate Identifier 2003-NM-103-AD]	MOUTING SYMBOL
RIN 2120-AA64	BOG ANMI 66
Airworthiness Directives; BAE Systems (Operations) Limited (Jetstream) Model 4101	DATE
Aimilana	ROUTING SYMBOL
AGENCY: Federal Aviation Administration (FAA), (DOT)	ANM 7 INITIALS/SIGNATURE
ACTION: Notice of proposed rulemaking (NPRM).	DATE 2 115 Jans
SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all	ROUTING SYMBOY
BAE Systems (Operations) Limited (Jetstream) Model 4101 airplanes. This proposed	INITIAL SIGNATURE
AD would require the overhaul of certain auxiliary components installed on the main	DATE 3/22/06
landing gear (MLG) and nose landing gear (NLG). This proposed AD is prompted by	ROUTING SYMBOL
manufacturer determination that life limits currently approved for certain auxiliary	INITIALS/SIGNATURE
components of the MLG and NLG could result in these components exceeding overhaul	DATE
threshold limits and possibly failing. We are proposing this AD to prevent failure of the	POUTING SYMBOL
MLG or NLG, and consequent damage to the airplane and injury to flightcrew and	INITIAL ASSIGNATURE
passengers.	3/30/05
DATES: We must receive comments on this proposed AD by [insert date 30 days after	ROUTING SYMBOL
date of publication in the FEDERAL REGISTER].	INITIALS/SIGNATURE
ADDRESSES: Use one of the following addresses to submit comments on this propos	E TE
AD.	ROUTING SYMBOL
• DOT Docket web site: Go to http://dms.dot.gov and follow the instructions for	INITIALS/SIGNATURE
sending your comments electronically.	DATE